

**Agency Approval**

Factory Mutual Approved Intrinsically Safe for Hazardous Locations USA & Canada  
T3C Ta = -40°C to 82°C; T4 Ta = -40°C to 66°C  
CL I Zone 0 AEx/Ex ia IIC  
T3 Ta = -40°C to 82°C; T4 Ta = -40°C to 66°C

**Ranges and Resolution**

See table below. Engineering units are factory set.  
Resolution is fixed and limited to available display digits  
20, 200, 2000 ranges display 19.99, 199.9, 1999

*See DPG2000B D4 series for models with increased resolution, high accuracy option, and higher pressure ranges.*

**Accuracy**

Accuracy includes linearity, hysteresis, repeatability  
Accuracy:  $\pm 0.25\%$  of full scale  $\pm 1$  least significant digit  
Sensor hysteresis:  $\pm 0.015\%$  FS, included in accuracy  
Sensor repeatability:  $\pm 0.01\%$  FS, included in accuracy

**Display**

3 readings per second nominal display update rate  
3.5 digit (1999) LCD, 0.5" H digits  
**BL** models: LED display backlight. Hold front button to operate backlight.

**Batteries**

Two 1.5 V AAA (Panasonic LR03) alkaline cells  
**B:** Approx. 1000 hours  
**BL:** Approx. 150-1000 hours depending on backlight usage  
Low battery indication: "LOBAT" on display

**Auto Shutoff**

Factory set for 5 or 10 minutes

**Controls**

Front button turns gauge on and starts auto shutoff timer  
**BL** models: Front button turns gauge on and starts auto shutoff timer. Hold front button to operate backlight.

**Calibration**

Non-interactive zero and span pots,  $\pm 10\%$  of range  
Top-mounted potentiometers covered with reusable label

**Weight**

9 ounces (approx.), shipping wt. 1 pound (approx.)

**Housing Materials and Circuit Board Protection**

NEMA 2 gray coated aluminum case, rear cover, bezel  
Front and rear rubber gaskets, polycarbonate label  
Stainless steel stiffener plate to reinforce sensor area  
Conformal coating on circuit boards for moisture resistance

**Connection and Sensor Material**

1/4" NPT male fitting  
Sensor and all wetted parts are 316L stainless steel

**Overpressure, Burst, Vacuum Service**

3000 psig sensor: 5000 psig overpressure  
5000 psig sensor: 7500 psig overpressure  
All others: 2 X pressure range overpressure  
Burst pressure: 4 X sensor pressure rating, or 10,000 psi, whichever is less  
Vacuum service: 15 psig, 100 psig, 200 psig, 15 psia, 30 psia, 100 psia

**Environmental Temperatures**

Storage temperature: -40 to 203°F (-40 to 95°C)  
Operating temperature: See Agency Approval Section  
Sensor compensated range: 32 to 158°F (0 to 70°C)

- $\pm 0.25\%$  Test Gauge Accuracy

- 316L Stainless Steel Sensor

- All Metal Housing



Ranges and Resolution		The listed ranges are rounded off. Consult factory for special units									
psig vacuum	Res	oz/in² vacuum	Res	Torr absolute	Res	bar vacuum	Res	kPa vacuum	Res	g/cm² vacuum	Res
15PSIVAC	0.01	235ZINVAC	1	760TORRA	1	1BARVAC	0.001	100KPAVAC	0.1	1000GCMVAC	1
psi absolute	Res	oz/in² absolute	Res	1600TORRA	1	bar absolute	Res	kPa absolute	Res	g/cm² absolute	Res
15PSIA	0.01	240ZINA	1	mmHg vacuum	Res	1BARA	0.001	100KPAA	0.1	1000GCMCA	1
30PSIA	0.1	480ZINA	1	760MMHGVC	1	2BARA	0.001	200KPAA	0.1	2000GCMCA	1
100PSIA	0.1	1600ZINA	1	mmHg absolute	Res	7BARA	0.01	700KPAA	1	g/cm² pressure	Res
psig pressure	Res	oz/in² pressure	Res	760MMHG	1	bar pressure	Res	kPa pressure	Res	200GCMG	0.1
3PSIG	0.01	50ZING	0.1	1600MMHG	1	1BARG	0.001	20KPG	0.01	350GCMG	1
5PSIG	0.01	80ZING	0.1	mmHg pressure	Res	2BARG	0.001	35KPG	0.1	1000GCMG	1
15PSIG	0.01	240ZING	1	150MMHGG	0.1	4BARG	0.01	100KPG	0.1	2000GCMG	1
30PSIG	0.1	480ZING	1	260MMHGG	1	7BARG	0.01	200KPG	0.1	kg/cm² vacuum	Res
60PSIG	0.1	960ZING	1	760MMHGG	1	14BARG	0.01	400KPG	1	1KGCMVAC	0.001
100PSIG	0.1	1600ZING	1	1600MMHGG	1	20BARG	0.01	700KPG	1	kg/cm² absolute	Res
200PSIG	0.1	inH₂O vacuum	Res	mmH₂O pressure	Res	35BARG	0.1	1400KPG	1	1KGCMCA	0.001
300PSIG	1	400INH20VAC	1	2000MMH20G	1	70BARG	0.1	2000KPG	1	2KGCMCA	0.001
500PSIG	1	inH₂O absolute	Res	cmH₂O vacuum	Res	140BARG	0.1	MPa pressure	Res	7KGCMCA	0.01
1000PSIG	1	400INH20A	1	1000CMH20VAC	1	200BARG	0.1	0.7MPAG	0.001	kg/cm² pressure	Res
2000PSIG	1	850INH20A	1	cmH₂O absolute	Res	350BARG	1	1.4MPAG	0.001	1KGCMG	0.001
inHg vacuum	Res	inH₂O pressure	Res	1000CMH20A	1	atm vacuum	Res	2MPAG	0.001	2KGCMG	0.001
30INHGVC	0.1	85INH20G	0.1	2000CMH20A	1	1ATMIVAC	0.001	3.5MPAG	0.01	4KGCMG	0.01
inHg absolute	Res	140INH20G	0.1	cmH₂O pressure	Res	atm absolute	Res	7MPAG	0.01	7KGCMG	0.01
30INHGA	0.1	400INH20G	1	200CMH20G	0.1	1ATMA	0.001	14MPAG	0.01	14KGCMG	0.01
60INHGA	0.1	850INH20G	1	350CMH20G	1	2ATMA	0.001	20MPAG	0.01	20KGCMG	0.01
200INHGA	0.1	1700INH20G	1	1000CMH20G	1	7ATMA	0.01	35MPAG	0.1	35KGCMG	0.1
inHg pressure	Res	ftH₂O pressure	Res	2000CMH20G	1	atm pressure	Res			70KGCMG	0.1
6INHGG	0.01	7FTH20G	0.01	mbar vacuum	Res	1ATMG	0.001			140KGCMG	0.1
10INHGG	0.01	12FTH20G	0.01	1000MBARVAC	1	2ATMG	0.001			200KGCMG	0.1
30INHGG	0.1	35FTH20G	0.1	mbar absolute	Res	4ATMG	0.01			350KGCMG	1
60INHGG	0.1	70FTH20G	0.1	1000MBARA	1	7ATMG	0.01				
120INHGG	0.1	140FTH20G	0.1	2000MBARA	1	14ATMG	0.01				
200INHGG	0.1	200FTH20G	0.1	mbar pressure	Res	20ATMG	0.01				
400INHGG	1	230FTH20G	1	200MBARG	0.1	34ATMG	0.1				
600INHGG	1	480FTH20G	1	350MBARG	1	70ATMG	0.1				
1000INHGG	1	700FTH20G	1	1000MBARG	1	140ATMG	0.1				
2000INHGG	1	1150FTH20G	1	2000MBARG	1	200ATMG	0.1				

Note: Range codes display as follows:  
20 = 19.99  
200 = 199.9  
2000 = 1999  
For more display digits or 3000 PSIG and 5000 PSIG ranges see DPG2000B-D4 series

**Options**—add to end of model number. Factory installed only. See [cecomp.com/accessories](http://cecomp.com/accessories) for details.

-PM Panel mount, 4.1" x 4.1"

**Calibration Cert. Option**—add to end of model number

-NC NIST traceability documentation, 5 points and date

**Accessories**—order separately

**RB**

High visibility orange rubber boot protects gauge for portable applications.

**SCR14SS**

Filter screen fitting keeps debris out of gauge sensor. For food vacuum packaging applications. 303SS body, 100 micron 304SS screen.

**CON14SS**

Quick connector to install or remove gauge without tools. 304 stainless steel, urethane seal.



## Precautions

## Approved Locations

The DPG2000B series is approved for use in the following Hazardous Locations.

IS Class I Div 1 Gp ABCD

T3C Ta = -40°C to 82°C; T4 Ta = -40°C to 66°C.

CL I Zone 0 AEx/Ex ia IIC

T3 Ta = -40°C to 82°C; T4 Ta = -40°C to 66°C

## Installation

- ✓ Read these instructions before installing the gauge. Configuration may be easier before the gauge is installed. Contact the factory for assistance.
- ✓ Installation instructions must be strictly followed in compliance with Intrinsic Safety National Standard NEC 504 or ANSI/ISA RP 12.6 and the National Electrical Code.
- ✓ Outdoor or wash down applications require a NEMA 4X gauge or installation in a NEMA 4X housing.
- ✓ Use fittings appropriate for the pressure range of the gauge.
- ✓ Due to the hardness of stainless steel, it is recommended that a thread sealant be used to ensure leak-free operation.
- ✓ For contaminated media use an appropriate screen or filter to keep debris out of gauge port.
- ✓ Avoid permanent sensor damage! NEVER insert objects into gauge port or blow out with compressed air.
- ✓ Remove system pressures before removing or installing gauge.
- ✓ Install or remove gauge using a wrench on the hex fitting only. Do not attempt to turn by forcing the housing.

## Operation

- ✓ Use within the pressure range indicated on gauge label.
  - ✓ Avoid permanent sensor damage! Do not apply vacuum to gauges not designated for vacuum operation.
  - ✓ Use only with media compatible with 316L stainless steel.
  - ✓ Gauges are not for oxygen service. Accidental rupture of sensor diaphragm may cause silicone oil inside sensor to react with oxygen.
  - ✓ The DPG2000B series gauges must only be operated in specified ambient temperature ranges.
- Maintenance**
- ✓ The non-metallic cover of the pressure gauge is considered to constitute an electrostatic discharge hazard. Clean only with a damp cloth.
  - ✓ Batteries must be replaced when the low battery indication comes on to prevent unreliable readings.
  - ✓ **WARNING:** Replace batteries with approved type in non-hazardous locations only.
  - ✓ Approved batteries are two Panasonic LR03 1.5 V AAA alkaline cells. Replace both batteries at the same time.
  - ✗ **WARNING:** Substitution of batteries may impair intrinsic safety. Improper voltages will damage the gauge.
  - ✗ **WARNING:** Substitution of components may impair intrinsic safety. Do not modify the gauge.
  - ✓ These products do not contain user-serviceable parts except for batteries. Contact factory for repairs, service, or refurbishment.


## Battery Replacement

A low battery indication (either LOBAT or a symbol depending on the model) will be shown in the upper left-hand corner of the display when the battery voltage falls sufficiently. The batteries should be replaced when the indicator comes on or unreliable readings may result.

**WARNING:** Replace batteries with approved type in non-hazardous locations only. Replace batteries with two Panasonic LR03 1.5 V AAA alkaline cells.


Replace both batteries with new ones at the same time. Do not mix different types of batteries. Substitution of components may impair intrinsic safety.

1. Remove the 6 Phillips screws on the back of the unit.
2. Remove batteries by lifting up the positive end of the battery (opposite the spring) taking care not to bend the spring.
3. Discard old batteries properly, do not discard into fire, sources of extreme heat, or in any hazardous manner.
4. Install batteries with correct orientation. The negative (flat) end of each battery should be inserted first facing the battery holder spring.
5. Replace the back cover, including the rubber gasket.



DS-DPG2000B rev. 12-12

## Dimensions



Cecomp maintains a constant effort to upgrade and improve its products. Specifications are subject to change without notice. See [cecomp.com](http://cecomp.com) for latest product information. Consult factory for your specific requirements.

## Types of Gauges

Gauge reference reads zero with the gauge port open.

Sealed reference reads zero with the gauge port open and is referenced to 14.7 psi. Used for 500 psi and up.

Absolute reference reads atmospheric pressure with gauge port open and zero at full vacuum. With the gauge port open to atmosphere, it is normal for readings to fluctuate due to continuously changing barometric pressure.

## Operation

Press the button on the front of the gauge to activate the display. The pressure readings are then displayed and updated approximately 3 times per second.

The gauge will stay on for a period of time determined by the auto shutoff time. After this time the gauge will automatically shut off to conserve battery life.

## Display Backlighting (BL models only)

Display backlighting can be turned on by pressing and holding the front button. When the button is released the display backlight turns off. Frequent use of the display backlight shortens battery life.

## Calibration Preparation

Calibration must only be done in a non-hazardous area. See Installation and Precautions above.

Gauges are factory calibrated at approximately 23°C using NIST traceable calibration equipment. Calibration is not required before using the gauge.

Calibration intervals depend on your quality standards, but annual re-calibration is customary. Calibration should be performed by qualified individuals using appropriate calibration standards and procedures.

Gauges can be returned to the factory for recalibration and repairs. NIST traceability is available.

The calibration equipment should be at least four times more accurate than the gauge being calibrated and be able to generate and measure pressure and/or vacuum over the full range of the gauge.

A vacuum pump able to produce a vacuum of 100 microns (0.1 torr or 100 millitorr) or lower is required for vacuum and absolute gauges.

Warning: Never apply vacuum to gauge not designated for vacuum service. Permanent sensor damage may result.

Install fresh batteries.

Allow the gauge to equalize to normal room temperature for approximately 20 minutes before calibration.

For an as-found report, record readings at three to five points over the range of gauge.

## Calibration

See calibration preparation section. See rear label of gauge for potentiometer identification, model identification and pressure range.

Remove calibration label to expose opening with calibration potentiometers. This label may be reused many times if kept clean.



Zero calibration should be done before span calibration. Zero and span are non-interactive. It is possible to do zero calibration only.

## Zero for gauge reference ranges

With the pressure port open to the ambient, adjust the Zero control until the gauge reads zero with the “-” sign occasionally flashing.

## Zero for absolute reference gauges

Apply full vacuum to the gauge. Adjust the Zero potentiometer to match the gauge's display to your calibrator's absolute vacuum reading. It may be zero or close to it depending on the ability of the vacuum pump.

## Span for all gauges

A pressure setting that is 75% of full scale works well to minimize mid-range non-linearity.

Adjust the span potentiometer to match the gauge's display to your calibrator's reading.

## Verification

Verify pressure indications at 0%, 25%, 50%, 75%, and 100% of full scale and repeat calibration as needed to achieve best accuracy over desired operating range.

Replace the calibration label when done.